



Hyundai Auto Canada Corp.  
75 Frontenac Drive, Markham, ON, Canada L3R 6H2

Transport Canada: 2018-095  
Hyundai Auto Canada: R0152

## SAFETY RECALL NOTICE

Dear Hyundai Tucson Owner:

This notice is sent to you in accordance with the requirements of the Motor Vehicle Safety Act.

Hyundai has decided that a defect which relates to motor vehicle safety exists in your vehicle, with the VIN shown above. Hyundai is conducting a safety recall in Canada to inspect, and if necessary, replace the engine assembly in Certain Model Year 2011 through 2013 Hyundai Tucson vehicles equipped with 2.4 liter engines produced from May 1, 2010 to December 31, 2012 by Hyundai Motor Company at the Ulsan plant in the Republic of Korea.

Our records indicate that your vehicle is affected.

We request that any vehicle lessor receiving this recall notice forward a copy of this notice to the lessee.

### What is the problem?

- The subject vehicles may have an engine oil leak from the seal between the oil pan and engine block which, if left unrepaired and operated over time, could eventually lead to engine damage. A damaged engine could lead to a high-speed stall, increasing the risk of a crash. It could also increase the risk of a vehicle fire.

### What should you do?

- **We urge you to call your Hyundai dealer to schedule an appointment so the dealer may perform this recall on your vehicle. Please refer to Recall 91C012 (R0152) when making this appointment.** This procedure will be performed at **NO CHARGE** to you.

For a list of Hyundai dealers, please visit [www.hyundaicanada.com](http://www.hyundaicanada.com).

### What will Hyundai do?

- Your Hyundai dealer will replace your vehicle's engine oil pressure switch with a new one. The dealer will also inspect the engine's oil pan, and if necessary, replace the oil pan. This procedure will be performed at **NO CHARGE** to you.

We recommend scheduling a service appointment to minimize inconvenience.

### What if you have other questions?

- If you have previously paid for repairs related to this recall, please visit your Hyundai dealer, and bring along the receipts for these earlier repairs.

If you require further assistance, you may contact the Hyundai Auto Canada Corp. Customer Relations Department at the following toll-free telephone number: 1-888-216-2626 (French or English).

We urge your prompt attention to this important safety matter.

Hyundai Auto Canada Corp!